

Ms. Gwen Gaal Johnson Controls Building Technologies and Solutions San Antonio, TX Plant 5680 East Houston Street San Antonio, TX 78220

Re: HSB Registration Services Certificate Q 274 Continuance of Certification due to an extraordinary event

Dear Ms. Gaal,

This is in response to the request to postpone the recertification audit past the certification expiration date due to the COVID-19 pandemic.

The request has been approved. Therefore the following dates and actions will apply:

- 1. The certification has been extended from 11/29/2020 to 06/29/2021.
- 2. The Recertification audit has been completed as a hybrid audit 12/20/2020 and 03/23-26/2021. The audit is now undergoing a certification committee review.

Should there be any questions regarding this information please contact me to discuss.

Best Regards,

Scott W Carey

Scott Carey

Cc: File, Auditor

13 April 2021

Scott Carey Certification Manager HSB Registration Services Tel.: +(502) 619-4142 Fax: +(484) 582-1802

Scott carey@hsb.com

The Hartford Steam Boiler Inspection and Insurance Co. Bay Colony Executive Park 595 East Swedesford Rd Wayne, PA 19087 www.munichre.com/HSB